

MAINTENANCE OPERATION No. 7

LUCAS R.M.12 LIGHTING AND IGNITION EQUIPMENT

SERIES A (Double Bank Rectifier) Fitted
prior to Engine No. 35334

SERIES B (Single Bank Rectifier) Fitted
from Engine No. 35334

LOCATION OF FAULTS AND TESTING PROCEDURE

The "Testing Procedure" Section is a reprint of Lucas Service Bulletin SB/GN/3, SB/GN/4 and other Bulletins regarding this equipment.

The "Location of Faults" Section is a reprint of the booklet issued with all Speed Twin machines. This information will be included in the Instruction Book when the next edition is published.

We cannot supply testing equipment such as voltmeters, ammeters, etc., but for the convenience of distributors and dealers 18 SWG nichrome wire is available from Service Stores in four-yard lengths.